

FIG. 1 (A)




FIG. 1 (B)




FIG. 2(A)

Surface roughness		
Ra	[ $\mu\text{m}$ ]	0.29
Ry	[ $\mu\text{m}$ ]	2.17
Rz	[ $\mu\text{m}$ ]	1.70
$\delta$	[ $\mu\text{m}$ ]	1.05
tp	[%]	36.72
Sm	[ $\mu\text{m}$ ]	6.75
S	[ $\mu\text{m}$ ]	1.34
RMS	[ $\mu\text{m}$ ]	0.36
Cut	[mm]	non

Measurement condition	
Dark cut	: non processed
Bright cut	: non processed
Smoothing	: simple $\pm 2$
Inclination	: Auto
correction	: Auto




FIG. 2(B)

Surface roughness		
Ra	[ $\mu\text{m}$ ]	0.30
Ry	[ $\mu\text{m}$ ]	2.18
Rz	[ $\mu\text{m}$ ]	1.83
$\delta$	[ $\mu\text{m}$ ]	1.15
tp	[%]	27.34
Sm	[ $\mu\text{m}$ ]	7.21
S	[ $\mu\text{m}$ ]	2.20
RMS	[ $\mu\text{m}$ ]	0.38
Cut	[mm]	non

Measurement condition	
Dark cut	: non processed
Bright cut	: non processed
Smoothing	: simple $\pm 2$
Inclination	: Auto
correction	: Auto




FIG. 3 (A)




FIG. 3 (B)




FIG. 3 (C)

